

Compressor Change



eTPB2129 | September 9, 2021

IMPORTANT DATES:

First Production:
See Table

First Ship:
As current inventory is depleted

Pricing Info:
Available

WARRANTY:
Registered Limited Warranty:
No change

Non-Registered Limited Warranty:
No change

RATINGS:
AHRI ratings available at AHRIDirectory.org

Reason for Update:

Increased demand is placing a strain on compressor supply. To ensure stable production and to improve product lead times, we will be using different compressors in the model numbers shown below. These compressors have a higher availability and will help alleviate some capacity constraints. Note that there will be new model numbers created as listed below.

Important Notes:

1. There is no change in AHRI Ratings between old and new models. AHRI ratings stop at the 9th model digit which is unchanged between the new and old models.
2. Replacement parts lists are complete and available in the system. All parts are existing production parts; no additional replacement parts are included with this release (note the changed replacement parts in the table below).
3. Pricing between the new and old model numbers are the same.
4. Please note any differences in breaker sizing in the table below.

Model Change/ Updates:

Current Production Model # (From)	New Model # (To)	Current Breaker	New Breaker	Updated Replacement Part Number	Production Start
4TTR4036L1000AA	4TTR4036L1000BA	30	30 (no change)	COM11967	9/15/2021
4TTR4037L1000AA	4TTR4037L1000BA	30	30 (no change)	COM11967	9/15/2021

