

Compressor Change

eTPB2130 | September 24, 2021

IMPORTANT DATES

First Production:

See Table Below

First Ship:

As Current Inventory is Depleted

Pricing Info:

Available

WARRANTY:

No Change

RATINGS:

AHRI ratings available at AHRIDirectory.org

Reason for Update: Increased demand is placing a strain on compressor supply. To ensure stable production and to improve product lead times, we will be using different compressors in the model numbers shown below. These compressors have a higher availability and will help alleviate some capacity constraints. Note that there will be new model numbers created as listed below, including one model number revision: 4TTR3036H1000PA will revert to 4TTR3036H1000NA.

Important Notes:

1. There is no change in AHRI Ratings between old and new models. AHRI ratings stop at the 9th model digit which is unchanged between the new and old models.
2. Replacement parts lists are complete and available in the system. All parts are existing production parts; no additional replacement parts are included with this release (note the changed replacement parts in the table below).
3. Pricing between the new and old model numbers are the same.
4. Please note any differences in breaker sizing in the table below.

Model Changes/Updates:

New / Prior	Current Production Model # (From)	New/Prior Model # (To)	Current Breaker	New Breaker	Updated Replacement Part Number	Production Start
Prior	4TTR3036H1000PA	4TTR3036H1000NA	35	30 (no change for prior unit)	COM11968	10/25/2021
New	4TTR3024H1000NA	4TTR3024H1000PA	30	20	COM11996	11/1/2021

