

Compressor Change

eRTPB2110 | September 24, 2021



IMPORTANT DATES

First Production:

See Table

First Ship:

As current inventory is depleted

Pricing Info:

Available

WARRANTY:

No Change

RATINGS:

AHRI ratings available at AHRIDirectory.org

Reason for Update:

There's an increased demand for compressors and to alleviate the capacity constraint, new compressors will be used in the models listed below which will change the current model numbers to a new model number. Using these new compressors will improve lead times and increase product availability.

Important Notes:

- The models listed below will remain as scroll compressors. We are only changing supplier for these units to increase product availability
- There is no change in AHRI Ratings between the new and old models. AHRI ratings stop at the 9th model digit which is unchanged between the new and old models.
- Replacement parts for the prior model are still active and valid in the system. Note the changed replacement part in the table
- Pricing between the new and old model numbers are the same.
- Please note the move to lower breaker/ fuse from Wire Harness and existing Compressor Model Number Change. The bulletin is just highlighting the move from Wire Harness to Lower Breaker / Fuse and the existing and new compressor model numbers.

Model Change/Updates:

New/Prior	Current Production Model # (From)	New/Prior Model # (To)	Current Breaker (From)	New Breaker (To)	New Compressor Model	Production Start
New	A4AC3023A1000BA	A4AC3023A1000CA	30	20	LBA020	11/1/2021
New	A4AC3024A1000BA	A4AC3024A1000CA	30	20	LBA020	11/1/2021
New	A4AC4023A1000BA	A4AC4023A1000CA	30	20	LBA020	11/1/2021
New	A4AC4024A1000BA	A4AC4024A1000CA	30	20	LBA020	11/1/2021